



**ADDENDUM:**

**#2**

**TODAY'S DATE:**

**8/14/2024**

**PROJECT NAME:**

**CASCADE HOMES ATTIC REPAIRS**

**CONTACT / TITLE:**

**DON HATFIELD**

**PROJECT MANAGER**

**PHONE / EMAIL:**

**206.574.1213**

**donaldh@kcha.org**

**This Addendum is used to Identify Items in the Original Documents with Action as Follows:**

**BID**

**RFQ**

**RFP**

**CLARIFY**

**CHANGE**

**DELETE**

**ADD**

**SUBSTITUTE**

**1 Page(s) Total for this Addenda, including this page.**

**CHANGE:**

- 1. Section 001010 Division 6 Woods and Plastics Rough Carpentry #2 A new access door (total of 108) will be installed in each tenant's hallway. Change count to a (total of 58) access doors.**
- 2. Division 09 Finishes -092100 Gypsum Board Assemblies to read 092116 Gypsum Board Assemblies**

**QUESTION:**

**"We would like to bring to your attention that during the walk through, my Project Manager saw mold in the attic. How would you like that to be addressed in the bid?"**

**ANSWER:**

**Per the Scope of Work: "Since organic growth was likely observed on the wood framing and plywood sheathing, the Contractor is to use best management practices when conducting any work in the attic spaces."**

**END OF ADDENDUM # 2**